

COLDMASTER® INSTRUCTIONS

How To Freeze/Use:

1. Wash with hot water and mild detergents.
2. **For optimum performance, freeze unit at 0°F (-18°C) for a minimum of 8 hours.**
3. Fill the **Coldmaster®** unit with **refrigerated** product that is at or below 40°F (4°C). **Coldmaster®** units, with the exception of the Coldbowl, will then maintain a temperature below 40°F (4°C) for a minimum of 8 hours. This 40°F (4°C) temperature is based on a 76°F/24°C ambient room temperature.

When using all Coldpans: These units will maintain 40°F (4°C) or below for 8 hours.

When using Coldcrock CM1030: Maintains below 40°F (4°C) temperature for 8 hours.
May be placed on enclosed *Coaster* to catch condensation.

When using Coldbowl CM1050: This unit will maintain below
40°F (4°C) for up to 5 hours.

4. After use, wash with hot water and mild detergents. Refreeze for 8 hours. This “re-charges” the coolant formula for another 8 hours of service.

NOTE:

- **DO NOT HEAT UNITS IN OVEN OR PLACE ON TOP OF BURNERS.**
- Although the **refrigerant gel** is non-toxic, it is **not intended** for human **consumption**.

For more information on our **Coldmaster®** line, please refer to our **Coldmaster®** brochure or full service catalog.

U.S. PATENT NO. 4,981,234

Worldwide Headquarters:
P.O. Box 53006
Oklahoma City, Oklahoma 73152-3006
(405) 475-5600 • FAX (405) 475-5607
1-800-654-8210
www.carlislefsp.com

European Distribution Center:
Edisonstraat 84, P.O. Box 110
6900 AC Zevenaar, The Netherlands
Tel +31/(0)316-596550 • Telex 45642
FAX +31/(0)316-340168
#104803831 Rev. 3/02

CARLISLE
FoodService Products